



Segment 1F – Trail construction just north of Keebler Road at Volpi Commons



Segment 1F – View of trail with clearing and base stone placed on north side of Volpi Park



Segment 1F – View looking west as trail rounds Volpi Park



Segment 1F – View of south bridge crossing



Segment 2B – View of temporary bridge at end of Hansen Road



Segment 2B – West view of trail construction from Sweetbriar Park



Segment 2B – Looking west with trail clearing & stone base placed



Segment 2B – View of north bridge crossing area with Covered Bridge Road homes above



Segment 2B – View of trail construction looking north as trail leaves Covered Bridge Road



Segment 2B – East view of trail with clearing and stone base placed



Segment 2B – Trail construction looking towards north bridge crossing



Segment 2B – View of north bridge crossing area from south side



Segment 3A -- View looking north from Beidler Road



Segment 3A – Trail with clearing and base stone complete



Segment 3A – Temporary crossing near Henderson Road



Segment 3B – Abrams and Beidler Roads Handicap Ramp



Segment 3B – Walking into the park from Abrams Road



Segment 3B – Looking down Basins 3B.2 and the far 3B.1